



SUMP WASTE ACCEPTANCE POLICY

SOUTHERN IDAHO SOLID WASTE

PO Box 159 Burley, ID 83318

(208)432-9082

WWW.SISW.ORG



FAILURE TO COMPLETE ALL REQUIREMENTS MAY RESULT IN LOAD REFUSAL

The Southern Idaho Solid Waste District (SISW) accepts sump waste at the Milner Butte Landfill, Hub Butte Special Waste Facility, and Ohio Gulch Transfer Station. Acceptance is dependent on the review of source and lab data which is representative of the sump waste. All appropriate source information and lab work must be submitted to SISW for review prior to shipment. A certified lab analysis is good for 24 months from the date of testing. SISW has the right to refuse loads and/or require additional testing. Loads are also subject to random load inspections.

- 1) In order to comply with R.C.R.A 40 CFR part 261.3, the following lab analyses from an approved laboratory are required to characterize the waste:
 - Toxicity Characteristics Leaching Procedure (TCLP) for: Arsenic, Barium, Cadmium, Chromium, Lead, Mercury, Selenium, Silver.
 - pH Test
 - TPH Test (8015)
 - Flashpoint Test
- 2) Each load must be accompanied by a signed Waste Tracking/Source Profile Form.
- 3) Sump waste must be placed where directed by SISW Personnel
- 4) Only licensed pumpers will be allowed to pump at our sites.

TIPPING FEES		
Material	In-District	Out-of-District
Sump	\$30.00/ton	\$60.00/ton

Milner Butte Hours

Monday – Saturday
8:00 am – 4:30 pm

Ohio Gulch Hours

Monday – Saturday
8:00 am – 4:30 pm

Hub Butte Hours

Monday – Friday
9:00 am – 4:00 pm

Thank you for your cooperation. For additional information, please contact SISW at (208) 432-9082.